

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i>					PAGE 1 OF 1 <hr/> DATE 25 August 2008		
TO: Navigation Interests				FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Potomac River Fairfax County, Virginia					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Potomac River @ Alexandria Stations 0+000 to 6+385 Surveyed on 13 August 2008		300	1	24	10	20	21
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Average width of channel is 300'. Length of channel is reported to the nearest mile. Actual length of channel is 1.21 miles. LQ=E1301637.20, N415900.86 (10.4') MH=E1301845.49, N415668.35 (19.9') RQ=E1301901.61, N413.231.55 (21.0')							